



**NEVERWET®
FABRIC DWR**

DESCRIPTION

Rust-Oleum® NeverWet® Fabric DWR is a one-step, superhydrophobic, water repelling treatment designed to keep items dry longer. This crystal clear formula allows fabrics to breathe, while dramatically repelling water from the surface. NeverWet Fabric DWR preserves items against damaging moisture without changing the look or feel of the fabric.

NeverWet Fabric DWR is ideal for use on leather, suede, polyester, cotton/polyester blends and canvas fabrics.

PRODUCTS

SKU	Description	Size
282073	NeverWet Fabric DWR	Gallon
284300	NeverWet Fabric DWR	Quart

SPRAYING CONDITIONS

Use outdoors or in a well ventilated area. Use when temperature is above 50°F (10°C) and humidity is below 85% to ensure proper drying. Avoid spraying in very windy and dusty conditions.

PRODUCT APPLICATION

SURFACE PREPARATION

Surfaces must be clean and dry.

PRODUCT APPLICATION (cont.)

APPLICATION

Prior to applying material, test on the fabric in an inconspicuous area for colorfastness. NeverWet Fabric DWR may enrich lighter colored fabric with a slightly darker tone.

Pour into a general purpose, hand-held sprayer that sprays an average droplet size of 100 microns (semi-fine mist). For larger applications a standard garden sprayer set to a semi-fine mist may also be used. For OEM applications, air atomized spray or airless spray may be used. Follow the guidelines below. Odorless when dry. Apply coating on the surface until wet. Do not soak or allow to puddle. **NOTE:** If bubbles appear, lightly dab with a clean, lint-free rag. Re-apply seasonally or when needed. **Do not use near open flame.**

EQUIPMENT RECOMMENDATIONS

AIR-ATOMIZED SPRAY:

Equipment	Tip Size	Air Pressure	Pot Pressure	Delivery Rate
Siphon Feed	0.055	25-35 psi	NA	10 fluid oz./min.
Gravity Feed	0.055	25-35 psi	NA	10 fluid oz./min.
HVLP Siphon	0.055	50 psi	NA	4 fluid oz./min.
Pressure Feed	0.055	45 psi	5 psi	12 fluid oz./min.

AIRLESS SPRAY:

Fluid Pressure	Fluid Tip	Filter Mesh
2000-2500 psi	0.009-0.0011	100

THINNING

DO NOT THIN.

CLEAN UP

Use soap and water immediately after use. Flush spray lines **immediately** with water, followed by Rust-Oleum Thinner #160402 or Pure Strength 3599 Cleaner/Degreaser.

If it is desirable to remove the NeverWet fabric treatment, scrub the coated area thoroughly with soap and water.

**TECHNICAL DATA****NEVERWET® FABRIC DWR****PHYSICAL PROPERTIES**

		NEVERWET FABRIC DWR
Composition		Proprietary
Pigment Type		NA
Solvents		Mineral Spirits
Weight	Per Gallon	6.53 lbs.
	Per Liter	0.78 kg
Volatile Organic Compounds		Compliant nationwide
Recommended Dry Film Thickness (DFT) per Coat		Varies depending on fabric
Wet Film to Achieve DFT (unthinned material)		Apply material until a wet, sag free film is evident
Practical Coverage at Recommended DFT (assumes 15% material loss)		Up to 375 sq.ft./gal. Varies depending on fabric
Dry Times at 70-80°F (21-27°C) and 50% Relative Humidity	Touch	Varies depending on fabric
	Handle	Varies depending on fabric
	Fully Dry	4-8 hours
Shelf Life		2 years
Flash Point		114°F (45°C)
Safety Information		For additional information, see MSDS

Calculated values are shown and may vary slightly from the actual manufactured material.

The technical data and suggestions for use contained herein are correct to the best of our knowledge, and offered in good faith. The statements of this literature do not constitute a warranty, express, or implied, as to the performance of these products. As conditions and use of our materials are beyond our control, we can guarantee these products only to conform to our standards of quality, and our liability, if any, will be limited to replacement of defective materials. All technical information is subject to change without notice.